

Asset Code	Machine Hrs	Part No	Part Description	Position	Maint Description	Last Changed SMR	Next Due SMR	Component Hrs	Notes
LO307	8393	419-03-48101	RADIATOR,OIL COOLER AND AIR COOLER ASSEMBLY	1	Replace	0	16000	8393	-
LO307	8393	419-03-48110	RADIATOR CORE	1	Replace	0	16000	8393	-
LO307	8393	419-03-48120	HYDRAULIC OIL COOLER	1	Replace	0	16000	8393	-
LO307	8393	419-03-48130	AFTERCOOLER ASSEMBLY	1	Replace	0	16000	8393	-
LO307	8393	419-12-31110	DAMPER - COUPLING	1	Replace	0	16000	8393	-
LO307	8393	419-14-48152	TRANSFER OIL COOLER TUBE	1	Replace	0	16000	8393	-
LO307	8393	419-17-40000	TRANSFER ASSEMBLY	1	Replace	0	16000	8393	-
LO307	8393	419-18-31104	HST PUMP	1	Replace	3543	13543	4850	Changed out @3543 hrs 8-7-2014
LO307	8393	419-18-41200	HYDROSTATIC MOTOR P1	1	Replace	0	10000	8393	-
LO307	8393	419-18-41300	HYDROSTATIC MOTOR P2	2	Replace	0	10000	8393	-
LO307	8393	419-22-30010	FRONT AXLE ASSEMBLY	1	Replace	0	16000	8393	-
LO307	8393	419-22-31010	DIFFERENTIAL	1	Replace	0	16000	8393	-
LO307	8393	419-22-32020	FRONT AXLE - LHS	1	Replace	0	16000	8393	-
LO307	8393	419-22-32030	FRONT AXLE - RHS	2	Replace	0	16000	8393	-
LO307	8393	419-23-30010	REAR AXLE ASSEMBLY	2	Replace	0	16000	8393	-
LO307	8393	419-23-31010	DIFFERENTIAL	2	Replace	0	16000	8393	-
LO307	8393	419-23-32020	REAR AXLE - LHS	3	Replace	0	16000	8393	-
LO307	8393	419-23-32030	REAR AXLE - RHS	4	Replace	0	16000	8393	-
LO307	8393	419-43-37100	BRAKE VALVE	1	Replace	0	16000	8393	-
LO307	8393	419-64-35301	PRIORITY VALVE - STEERING	1	Replace	0	16000	8393	-
LO307	8393	419-64-35301	PRIORITY VALVE - STEERING	2	Replace	0	16000	8393	-
LO307	8393	600-861-6420	ALTERNATOR	1	Replace	0	8000	8393	-
LO307	8393	600-863-5111	STARTER MOTOR	1	Replace	0	7500	8393	-
LO307	8393	705-56-36051	MAIN HYDRAULIC PUMP	1	Replace	0	10000	8393	Change out steering pump @ 3543 hrs 8-7-2014
LO307	8393	707-00-0H470	STEERING CYLINDER	1	Replace	0	10000	8393	Pump Steering and Hoist - C/O Hoist and Steering pump due to bearing failure @ 3543 hrs on 8/7/14

LO307	8393	707-00-0H480	STEERING CYLINDER	1	Replace	0	10000	8393	-
LO307	8393	707-01-0AH40	LIFT CYLINDER	1	Replace	0	10000	8393	-
LO307	8393	707-01-0AH40	LIFT CYLINDER	2	Replace	0	10000	8393	-
LO307	8393	707-01-0AH51	TILT CYLINDER	1	Replace	0	16000	8393	-
LO307	8393	708-7R-00710	FAN DRIVE MOTOR	1	Replace	0	16000	8393	-
LO307	8393	709-93-13300	MAIN CONTROL VALVE	1	Replace	0	16000	8393	-
LO307	8393	6754-61-1010	WATER PUMP	1	Replace	0	8500	8393	Inspected @ 7426 hrs, Inspected OK, No damaged lines, No leaks, Operation ok
LO307	8393	6754-72-1012	FUEL INJECTION PUMP	1	Replace	0	8500	8393	Inspected @ 7426 hrs, September 2016, No play in pulley, Tension good, Belt good, Hoses OK, Operation OK
LO307	8393	6754-81-8160	TURBOCHARGER	1	Replace	0	8000	8393	-
LO307	8393	6754-B0-0021	ENGINE ASSEMBLY	1	Replace	0	16000	8393	-
LO307	8393	WA320PZ-6 A/C SY	A/C SYSTEM	1	Replace	0	8500	8393	Inspected @ 7426 hrs, September 2016, Inspected OK, No damaged lines, No leaks, Operation ok
LO307	8393	WA320PZ-6 ACCUM	HYDRAULIC ACCUMULATOR	1	Replace	0	8000	8393	Inspected @ 5355 Hrs Jan 2016 - Operation Ok, Requires Cab Filters - Pushed 2000 Hrs - Needs filter change
LO307	8393	WA320PZ-6 ATTAC	ATTACHMENT PIN/BUSH	1	Replace	0	16000	8393	-
LO307	8393	WA320PZ-6 AXLE B	AXLE BRAKES	1	Replace	0	16000	8393	-
LO307	8393	WA320PZ-6 AXLE B	AXLE BRAKES	2	Replace	0	16000	8393	-
LO307	8393	WA320PZ-6 AXLE B	AXLE BRAKES	3	Replace	0	16000	8393	-
LO307	8393	WA320PZ-6 AXLE B	AXLE BRAKES	4	Replace	0	16000	8393	-
LO307	8393	WA320PZ-6 FUEL I	FUEL INJECTOR SET	1	Replace	0	8000	8393	-
LO307	8393	WA320PZ-6 HARNE	HARNESSES	1	Replace	0	8000	8393	-
LO307	8393	WA320PZ-6 HITCH	CENTRE HITCH PIN ASSEMBLY	1	Replace	0	16000	8393	-
LO307	8393	WA320PZ-6 UNI JO	UNIVERSAL JOINTS	1	Replace	0	16000	8393	-