

Asset Code	Description	Start	Finish	Category	Delay	Hours
DA406	INSPECT A/CON OPERATION	11/08/2015 16:30	11/08/2015 18:00	E	O	1.5
DA406	REPLACE PASSENGER SEAT BELT, INPECT BACKLOG DEFECTS	13/08/2015 10:00	13/08/2015 11:30	F	P	1.5
DA406	charge fire suppression	16/08/2015 16:00	16/08/2015 17:00	H	P	1
DA406	wash down, crow bar off dirt	27/08/2015 09:00	27/08/2015 11:00	S	P	2
DA406	WASH AND MULTI POINT INSPECTION	01/09/2015 10:00	02/09/2015 18:00	S	P	20
DA406	WELD UP CRACKS IN CHASSIS AND TRAY_REMOVE SEAT AND FIT REPLACEMENT SEAT, REWIRE PLUGS_CHIP OUT BUILD UP DIRT OUT OF TRAY_TYRE INSP	03/09/2015 07:00	03/09/2015 13:00	F	P	6
DA406	LEVEL 2 FIRE SUPPRESSION INSPECTION AND START REPAIRS	03/09/2015 16:00	04/09/2015 15:30	S	P	8.5
DA406	mechanical check	06/09/2015 10:00	06/09/2015 12:00	F	P	2
DA406	inspect pos 5 duo cone leak	09/09/2015 15:30	09/09/2015 16:00	D	P	0.5
DA406	250hr service	24/09/2015 14:00	24/09/2015 16:00	S	P	2
DA406	replace operator seat	10/11/2015 10:00	10/11/2015 10:30	F	P	0.5
DA406	monthly major inspections	12/11/2015 10:00	12/11/2015 12:00	F	P	2
DA406	2000hr service and mechanical inspection	15/11/2015 06:00	16/11/2015 11:00	S	P	17
DA406	carry out engine valve set (monthly major)	15/11/2015 14:00	15/11/2015 16:00	M	P	2
DA406	replace hydraulic hose old u/s	17/12/2015 11:00	17/12/2015 14:30	H	U	3.5
DA406	A/C Checkover/Clean	18/03/2016 07:30	18/03/2016 09:30	E	P	2
DA406	repair flashing light inspect tyre pressures	30/03/2016 11:00	30/03/2016 12:00	E	O	1
DA406	Degas, replace Comp and Dryer, Pressure test, vac, Regas Replace Am/FM Replace E stop	31/03/2016 12:00	31/03/2016 17:15	E	P	5.25
DA406	LEVEL 1 FIRE SUPPRESSION SERVICE	09/04/2016 14:30	09/04/2016 15:30	S	O	1
DA406	tyre inspection and pressures	02/05/2016 12:30	02/05/2016 12:45	TUC	O	0.25
DA406	FAULT AM FM RADIO / TWOWAY FAULT	07/05/2016 09:30	07/05/2016 10:00	E	O	0.5
DA406	REPAIR TWO WAY ANTENNA	08/05/2016 15:00	08/05/2016 16:00	E	P	1
DA406	CLEAN COOLANT TANK / FLUSH OVER FLOW LINES	08/05/2016 16:00	08/05/2016 18:00	M	P	2
DA406	inspect cooling system and sample	16/05/2016 11:30	16/05/2016 12:00	M	O	0.5
DA406	Pos 3 side wall crack	20/05/2016 06:00	21/05/2016 14:00	TUC	U	20
DA406	Jack machine up as the parked location was very poor for jacking	03/06/2016 06:00	03/06/2016 10:30	TUC	U	4.5
DA406	C/O Pos 1 tyre	03/06/2016 10:30	03/06/2016 15:30	TUC	D	5
DA406	strip tyres from rims	11/06/2016 13:30	11/06/2016 16:30	TUC	O	3
DA406	replace two way ariel and check operation	22/06/2016 16:00	22/06/2016 17:00	F	O	1
DA406	install new 2 way antenna	24/06/2016 14:30	24/06/2016 15:30	E	O	1
DA406	Checked saved fault codes_ Brake accumulator pressures	25/06/2016 07:00	25/06/2016 07:30	E	U	0.5
DA406	Pos 1 Wheel retorque	25/06/2016 14:45	25/06/2016 15:00	TUC	P	0.25
DA406	Fire suppresion system is low on gas	27/06/2016 09:30	27/06/2016 10:00	F	P	0.5
DA406	Changed RH mirror	29/06/2016 14:30	29/06/2016 14:45	F	P	0.25
DA406	Reinstalled bonnet safety latch	29/06/2016 14:45	29/06/2016 15:00	F	P	0.25
DA406	Repair oil leak	09/07/2016 08:00	09/07/2016 09:00	H	P	1
DA406	Fit anti tamper tag and inspect fire suppression	09/07/2016 09:00	09/07/2016 10:00	F	P	1
DA406	adjust accummulator pressures	09/07/2016 13:00	09/07/2016 14:00	D	P	1
DA406	pressure test radiator	09/07/2016 14:00	09/07/2016 14:30	M	P	0.5
DA406	clean radiator	10/07/2016 11:45	10/07/2016 12:15	M	O	0.5
DA406	check coolant system	11/07/2016 09:15	11/07/2016 09:45	M	P	0.5
DA406	TEST DRIVE MACHINE. E03 CODE CAME UP WHEN MANUALLY CHAINGING TO 5TH GEAR	17/09/2016 15:30	17/09/2016 16:00	D	O	0.5
DA406	OH HIRE INSPECTION	18/09/2016 07:30	18/09/2016 11:30	S	P	4
DA406	REPLACE REAR VIEW MIRROR LHS LOWER	19/09/2016 13:00	19/09/2016 13:15	F	O	0.25
DA406	hydraulic steering fault, diagnostic test diff locks and engine and transmission speed sensors	21/09/2016 15:30	22/09/2016 14:00	H	U	10.5
DA406	HYDRAULIC ISSUES-STEERING AND HOIST - TUB NOT LOWERING - BRING IN TO WORKSHOP TO DIAGNOSE ONGOING ISSUES - NO PRESSURE GAUGES IN P	26/09/2016 15:30	27/09/2016 10:30	H	U	7
DA406	HOIST LOWERING FAULT. DROPEPD HYDRAULIC OIL. WATER AT BOTTOM OF HYDRAULIC OIL TANK. COMMON BREATHER CASE WAS ALSO FLOODED WITH V	28/09/2016 13:30	29/09/2016 07:00	H	U	5.5
DA406	HYDRAULIC FAULT - MONITOR CYCLE TIMES - STEERING LEFT TO RIGHT RIGHT TO LEFT FULL SWING 6SECONDS (SPEC IS 4-5 SECONDS. HOIST 15 SECON	29/09/2016 15:30	29/09/2016 17:30	H	U	2
DA406	CHECK CYCLE TIMES - STEERING AND HOIST IN SPEC. RELEASE TO OPERATIONS. SCHEDULE FLUSH OF HYDRAULIC OIL WHEN POSSIBLE	30/09/2016 05:30	30/09/2016 07:00	H	U	1.5
DA406	EOM TREAD DEPTHS AND CHECK AND ADJUST TYRE PRESSURES	02/10/2016 12:00	02/10/2016 13:30	TUC	P	1.5
DA406	DIAGNOSE HYDRAULIC OIL LEAK FROM VALVE/HOSE. BUILD HOSE AND REPLACE_repair hydraulic hose, change oil	04/10/2016 11:30	05/10/2016 07:00	H	O	7.5
DA406	brake accumulator fault repair and test	05/10/2016 07:00	05/10/2016 10:00	F	U	3
DA406	brake accumulator lost charge change out, diagnostic test park brake fault and repiir, repair hydraulic leak, steering fault, steering locking whilts operating, CHECK	10/10/2016 10:00	14/10/2016 12:00	E	P	44
DA406	hydraulic temp fault	10/10/2016 14:00	10/10/2016 17:30	E	U	3.5
DA406	FIT SEAT	14/10/2016 12:00	14/10/2016 13:00	F	P	1

DA406	FIT DIFF TEMP SWITCH	14/10/2016 13:00	14/10/2016 14:00	D	P	1
DA406	HYDRAULIC OIL LEAK	20/10/2016 14:00	20/10/2016 17:30	H	O	3.5
DA406	Wash out radiator	13/11/2016 08:30	13/11/2016 09:00	M	P	0.5
DA406	Check and adjust Tyre pressures	13/11/2016 09:00	13/11/2016 09:15	TUC	P	0.25
DA406	Diagnose hoist fault, requires new lift cylinder	15/11/2016 14:00	23/11/2016 17:30	H	P	99.5
DA406	500hr service and mech check	24/11/2016 05:30	24/11/2016 12:30	S	P	7
DA406	Waiting on steering relief valve (machine Ok to be used if required)	24/11/2016 12:30	27/11/2016 17:30	H	P	41
DA406	Waiting on steering relief valve (machine Ok to be used if required)..No parts, fitted valve from DA415	28/11/2016 05:30	02/12/2016 09:30	H	P	52
DA406	Failed park brake switch	06/12/2016 09:00	06/12/2016 12:00	D	U	3
DA406	Steering still playing up after steering relief fitted, we will diagnose further	14/12/2016 05:30	23/12/2016 18:00	H	P	120
DA406	Steering valve faulty - we are removing one from a truck in Maddington	03/01/2017 05:30	29/01/2017 17:30	H	P	324
DA406	Steering valve faulty	30/01/2017 05:30	30/01/2017 15:00	H	P	9.5
DA406	Hoist fault still with unit	03/02/2017 09:30	03/02/2017 17:30	M	U	8
DA406	Check hoist fault	06/02/2017 05:30	11/09/2017 17:30	M	P	2388