



Vehicle History Summary

Quadrio Earthmoving

Fleet #	RT06
Registration	CGG292E
Make	Mack
Model	TITAN
VIN / Chassis #	6FMB05C044D709889
Build Date	2004

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-626	13/03/2019			AIRCON	Thermostat switch faulty. Replaced with new one and tested pressures. Checked vent temp. Working condition.	
R-606	26/02/2019	633342		GASKET, INJECTORS	Checked injectors etc, found engine damaged and coolant leaking into cylinders. Drained coolant, filled with clean water and cooling system sealer (irontite)-ran until sealed. Changed oil and filter. Carried out roadworthy and wear/tolerances inspection.	
R-313	21/01/2019			HEADLIGHTS	Completed-as per Rodney's advice	
R-315	18/01/2019			DOOR LATCH	Made up rod to right latch and made swivel. Removed fuse box. Paint and bolted ECM's up, wired fuse board.	
R-314	18/01/2019			BELTS	Belts adjusted up.	
R-464	17/01/2019			BUSHES	Removed torque rod bushes	
R-371	14/01/2019			BRAKES, DIFFERENTIAL	Repaired front diff oil leak Replaced air bag fitting Readjusted LHR brake Fitte new top radiator mount rubber	
I-45	13/01/2019			WAHVA Roadworthy Inspection	ROADWORTHY COMPLETE	
R-274	24/11/2018	629015		FUEL TANK	Welded bonds around tank Removed tank and fuel and washed out Weld up with bands right round in three positions. Paint tank	
S-45	23/11/2018	629015	16609	A	500hr Service complete Fixed wiring to diagnostics plug and test connect to computer. Replaced barometric sensor on motor. Rev gauge new relay 12v. Cleaned up ignition wire studs for power. Broken wires to ECM. Belts tightened Front was low due to housing leak Brake lining-6mm	

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-125	28/10/2018	625328	0	BATTERY, BEARING, BELTS, RADIO	Bearing inspected-no need for replacement. Tightened belts Fixed am/fm radio cleaned battery terminals Tightened radiator mounting rods	
R-125	28/10/2018	0	0	AIR BAG, SENSOR	Air bag does not need replacing-not leaking. Has very slight clap Replaced low pressure sensor	
R-46	17/10/2018	0	0	AIRCON	Checked AC drive belts-all tight and in good condition. Fuses all OK Without any AC gauge or charging equipment, unable to check system properly . Waiting for Maint coordinator to organise repairs. **REPAIR CLOSED AS ALL ITEMS WERE COMPLETED ON ANOTHER JOB CARD**	QUADRIO EARTHMOVING PTY LTD
R-191	16/10/2018		5253	AIRCON, AIR FILTER, AIR LEAK, EXHAUST, FAN BELT, LIGHTS, SWITCHES	Headlights low & high beam-repaired circuit & tested Driving lights 12v delay in dash-replaced and tested No power to AC thermostat or pressure switch-put after market switch on dash LHR tail light replaced Replaced both uni's on jack shaft Repaired air leaks under cab-hoses melted by exhaust Replaced exhaust system with 1 stack Replaced diff, trans & engine oil Replaced outer air filter Repaired tipper control switches Replaced both sets of fan belts Repaired tank step mount on RH front tank Repaire LH front mudguard Red dot fan not working-wired up and gassed Secured primary fuel filter housing Replaced fuel priming pump	
I-23	13/10/2018			Wear & Tolerances Inspection/Record		
S-16	12/10/2018	0	5233	B	B service complete. No fleet ID stickers Belts replaced V-belts replaced Replaced outer air filter Changed front & rear diff oils Changed transmission oil & replaced filter Repaired LHF mudguard Changed air compressor filter Repaired all air system leaks Replaced power steering filter Secured primary fuel filter housing Replaced priming pump Repaired fault R46, R125	
R-141	22/09/2018	0	0	BREAKDOWN	Checked over vehicle for obvious signs of b/down. Bled fuel system	
R-148	21/09/2018	0	0	HOSE	Removed & replaced top radiator hose from engine to top hose pipe	

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-34	09/08/2018	0	0	WATER PUMP		QUADRIO EARTHMOVING PTY LTD
R-61	31/07/2018	0	0	BONNET	replaced both snapped bonnet stop cables	QUADRIO EARTHMOVING PTY LTD
I-12	22/06/2018	593073	593073	WAHVA Roadworthy Inspection		
R-563				RADIATOR, TAILSHAFT		

Signed: _____

Name: _____

Date: _____

NOT VERIFIED