



# Vehicle History Summary

Quadrio Earthmoving

Fleet #	RT07
Registration	1BUO700
Make	Mack
Model	TITAN
VIN / Chassis #	6FMB05C043D709807
Build Date	2003

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-636	19/03/2019			MUDGUARD	Pulled rubber matt back. Set the bar up and tightened. Pulled the matt back over and all good	
R-635	19/03/2019			BRAKE BOOSTER	Found that LHR brake booster was leaking. Removed brake booster. Set up new brake booster and installed. Tested-all good	
R-634	19/03/2019			AIRCON	Clutch was seized on compressor. Removed compressor from truck. Installed new compressor. Installed hoses with new o-rings. Installed belts and adjusted. Vacced down, gassed up air con. Ran up and tested. All good.	
S-90	18/03/2019	0	0	B	SERVICE COMPLETE	
R-614	12/03/2019			DIFFERENTIAL, UNI JOINT	Drained front diff oil. Removed axles and components hooked to front diff. Removed front diff. Put sealant on mating surface and installed diff. Hooked component to diff. Replaced front and rear torque rods. Installed axles. Filled with diff oil. Replace the uni joint on the front drive shaft at the centre bearing. PTO was leaking oil over the ground. Removed PTO from transmission. Swapped fittings. Installed new PTO. Hooked up hoses. Topped up the hydraulic oil.	
R-603	26/02/2019			AIR CON, COMPRESSOR	Hook gauges to AC system. Front seal on air compressor faulty. Remove RT05 compressor and fit to machine. Vac and gas with 1.8kg R134A- vent temp 7.8 degrees. Fit old compressor back into RT05 so it can be moved still.	

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-583	18/02/2019			FUEL LINE, GASKET	Inspected radiator, pressurised radiator and was leaking around top LH side of tank around the gasket. Gasket needs replacing. Fuel hose from cooler to transfer pump has rubbed through again. When new hose is made it either needs a 90degree fitting put on cooler side or the piece of metal ground out which it is rubbing on.. Bonnet spring wore through mount. Drilled new hole in mount and put spring back on-all good	
R-567	14/02/2019		166993	RADIATOR CHANGEOUT	Refit radiator multiple bolts were missing, found replacements and fitted	
R-537	07/02/2019		63358	CLUTCH, FAN HUB, WHEEL SEAL	Replace RHR wheel seal Adjusted clutch Greased fan hub Greased all points on truck Topped up diffs with oil Replaced mudflap LH front washed	
R-514	24/01/2019			BONNET	Fitted bonnet straps to bonnet of truck and tested out.	
R-653	24/01/2019		6184	BONNET	Fitted bonnet straps to bonnet of truck	
R-366	24/01/2019			FUEL LINE	Fuel line from RT05 fitted to truck. New fuel line to go on RT05 when arrives. Both trucks are fixed-all good.	
R-316	11/01/2019			ENGINE CHANGEOUT	Removed motor and replaced with Brute Motor	
R-302	04/12/2018		160834	AIR BAG CONTROL, AIR LEAK, BUSHES, CLUTCH, UNI JOINT	Replaced uni joint at the rear of the centre bearing (had to oxy out and use port power to push out caps) Replaced torque rod on rear diff with universal unit with replaceable bushes Air leak at RHR brake booster replaced with unit, adjusted brakes. Fitted new air bag adjuster rod bushes Adjusted clutch on fulcrum arm (pressure plate adjustment seized)	
R-290	01/12/2018	160446		DOOR LATCH, OIL LEAK	Removed RH rear wheel, clean up, replaced brake shoes, wheel seal, removed steering column and replaced uney joint and bearing. Fixed door RH side, fixed door LH side. Replace boost hose and clamps	
S-42	24/11/2018	1601843	0	A	SERVICE COMPLETE Brake lining wear-8mm	

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-268	20/11/2018			SENSOR	Connect computer and go through codes, no codes logged or no active codes. Went for drive while computer was hooked up, monitored parameters-All ok. Speedo was intermittent which could cause the engine to derate. Issue resolved	
R-193	30/10/2018			SEAT, SNORKEL	seat re bolted/ snorkel tightened	
R-192	30/10/2018			BRAKES, BRAKE SHOES, OIL LEAK	brakes replaced / oil leak fixed as per Todd's advice	
R-202	22/10/2018			FUEL TANK	Hooked up ET & checked codes-No codes Removed & welded up fuel tank. Refitted tank	
T-2	17/10/2018	0	0	New	TIRES 7 & 8 REPLACED	
R-49	17/10/2018	155562	0	OIL LEAK	Checked fault, slight leak coming from LHF shocky-needs replacing. Added part to July stock as no part on site. 18/10/18 LH shock absorber replaced LH headlight & assembly removed off old mack. Checked-all lights ok.	QUADRIO EARTHMOVING PTY LTD
S-32	17/10/2018	0	0	C	2000hr Service complete Repaired bonnet mounts Replaced door hinge RH Replaced tyres no 7 & 8 **Rear brake shoes need to be replaced, slight leak in front diff***	
R-62	27/08/2018	141663	5146	AIR LEAK, BATTERY, FUEL TANK, PASSENGER	rEPAIRED RADIATOR MOUNTS REPLACED BOLTS ON BULL BAR MOUNT MADE UP LID FOR RH SIDE TOOLBOX. REMOVED AND REPLACED TANK STRAP LH SIDE. ADJUSTED BRAKES AND CHECK LINEINGS AND AIR LEAKS. NEED 2X PRESSURE SENSOR IN CAB & 2X JOSE JOINER REAR AXLE REAPLCED AIR CLEANSER REPAIRED LH SIDE AIR INTAKE. FIXED AIR LEAK ON GREASE SPLITTER. REPLACED LIGHTS THAT WEREN'T WORKING	QUADRIO EARTHMOVING PTY LTD
R-13	27/08/2018			EXHAUST, Lights	LIGHTS REPAIRED	
I-10	21/06/2018	132388	132388	WAHVA Roadworthy Inspection		
R-568				FUEL LINE, INJECTORS	hose needs a 90 degree fitting	
R-593		0	0	AIR BAG CONTROL		
R-594		0	0	AERIAL		Westrac Pty Ltd

Signed: \_\_\_\_\_

Name: \_\_\_\_\_

Date: \_\_\_\_\_

NOT VERIFIED