

Asset Code	Description	Start	Finish	Category	Delay	Hours
DA412	mechanical inspection	04/09/2015 08:00	04/09/2015 11:00	F	P	3
DA412	repair fuel leak from fuel pump fittings	04/09/2015 11:00	04/09/2015 12:00	M	U	1
DA412	air in fuel system	18/09/2015 15:00	18/09/2015 16:00	M	U	1
DA412	fuel starvation fault 2	19/09/2015 10:00	19/09/2015 12:00	M	U	2
DA412	fuel starvation fault 2_repair fuel pump electrical fault, diagnostic test electrical park brake fault_repair fuel pump electrical fault, diagnostic test electrical park b	20/09/2015 06:00	01/10/2015 18:00	M	U	98
DA412	inspect engine light on	10/10/2015 12:00	10/10/2015 13:00	E	P	1
DA412	inspect transmission leak and repair	12/10/2015 13:00	12/10/2015 14:00	D	P	1
DA412	Batteries U/S engine run fault, hoses leaking from centre hitch	24/10/2015 06:00	31/10/2015 18:00	M	U	96
DA412	Batteries U/S engine run fault, hoses leaking from centre hitch - waiting on parts	01/11/2015 06:00	04/11/2015 12:30	M	U	48
DA412	fuel fault clean fuel system repair fuel ipck up	16/11/2015 13:45	17/11/2015 11:30	M	P	10.25
DA412	Engine valve set	25/12/2015 13:00	25/12/2015 14:00	M	P	1
DA412	DIAGNOSE FIRE SUPPRESSION SYSTEM LEAK_COMMENCE ON HIRE INSPECTION_FIRE SUPPRESSION LEAK - DIAGNOSE AND REPAIR LEAKING AT HOSE CON	01/10/2016 15:30	03/10/2016 11:30	E	P	6
DA412	COMPLETE ON HIRE INSPECTION AND RECHARGE AFFF	03/10/2016 15:30	03/10/2016 17:00	S	P	1.5
DA412	on hire inspection, full grease machine, prep to change all axle oils from un-finished service_change out diff and final drive oils	05/10/2016 07:00	07/10/2016 12:30	F	P	15.5
DA412	MACHINE INSPECTION	12/10/2016 13:30	12/10/2016 13:45	F	O	0.25
DA412	REPAIR HYDRAULIC LEAK	12/10/2016 15:00	12/10/2016 15:15	H	O	0.25
DA412	RESEAL ACCUMULATOR	12/10/2016 15:15	12/10/2016 17:00	H	O	1.75
DA412	AFFF TOP UP	20/10/2016 11:00	20/10/2016 12:00	F	O	1
DA412	HYDRAULIC OIL LEAK	20/10/2016 12:00	20/10/2016 13:00	H	O	1
DA412	TOP UP FIRE SUPPRESSION	24/10/2016 06:30	24/10/2016 07:00	F	O	0.5
DA412	CHANGE OUT FUEL FILTERS DUE TO ACTIVE FUEL FAULT CODE	26/10/2016 15:30	26/10/2016 16:30	M	U	1
DA412	2 WAY REPAIR	27/10/2016 07:00	27/10/2016 07:15	E	O	0.25
DA412	CHANGE OUT UHF CRIMPS_SECURE VOLTAGE REDUCER	27/10/2016 15:30	27/10/2016 16:00	E	O	0.5
DA412	C/O Gauges and Refill, Charge	30/10/2016 13:00	30/10/2016 17:00	E	P	4
DA412	fuel system fault inspect and test	31/10/2016 12:30	31/10/2016 14:00	M	U	1.5
DA412	repair fuel leak from common rail pressure limiter	31/10/2016 14:00	31/10/2016 15:00	M	O	1
DA412	Check Hyd Leak	12/11/2016 13:00	12/11/2016 14:45	H	P	1.75
DA412	Pump up tyre	12/11/2016 14:45	12/11/2016 15:00	TUC	P	0.25
DA412	Wash out radiator	13/11/2016 09:30	13/11/2016 10:00	F	P	0.5
DA412	Check and grease drive shafts	15/11/2016 10:00	15/11/2016 10:15	D	P	0.25
DA412	Engine fault	15/11/2016 16:00	15/11/2016 16:30	M	U	0.5
DA412	LOST FUEL PRESSURE_ PRIME FUEL SYSTEM	16/11/2016 09:30	16/11/2016 09:45	M	U	0.25
DA412	Fuel fault on ramp	21/11/2016 09:00	21/11/2016 10:00	M	U	1
DA412	2000hr service and mech check	26/11/2016 05:30	26/11/2016 17:30	S	P	12
DA412	Top up gas in fire suppression	30/11/2016 08:00	30/11/2016 08:30	F	P	0.5
DA412	Repair oil leak	02/12/2016 06:00	02/12/2016 07:00	H	P	1
DA412	Top up fire suppression	08/12/2016 07:30	08/12/2016 08:00	M	P	0.5
DA412	Fire suppression went off - found leak at ground level actuation button	13/12/2016 05:30	13/12/2016 17:30	F	U	12
DA412	Fire suppression went off - still trying to find leak	17/12/2016 10:30	19/12/2016 10:00	F	P	23.5
DA412	Air in fuel system	04/01/2017 15:30	04/01/2017 16:00	M	U	0.5
DA412	Electrical fault	06/01/2017 13:00	06/01/2017 17:30	E	U	4.5
DA412	Backlog repairs	18/01/2017 14:00	18/01/2017 16:00	M	P	2
DA412	Remove hyd tank to repair crack	01/02/2017 05:30	08/02/2017 15:00	M	P	93.5
DA412	Parts required for fuel presure valve	27/02/2017 05:30	22/03/2017 15:00	M	P	285.5
DA412	Fuel pressure switch faulted again	23/03/2017 17:00	24/03/2017 17:00	E	U	12
DA412	Fuel pressure switch faulted again	23/03/2017 17:00	24/03/2017 17:00	E	U	12
DA412	Parts required for fuel presure valve	28/03/2017 05:30	28/03/2017 17:30	M	P	12
DA412	Parts required for fuel presure valve	28/03/2017 05:30	28/03/2017 17:30	M	P	12
DA412	Check fault with error code coming up - couldn't fault so will put back to work and check tomorrow	30/03/2017 14:00	30/03/2017 17:00	M	U	3
DA412	Check fault with error code coming up - couldn't fault so will put back to work and check tomorrow	30/03/2017 14:00	30/03/2017 17:00	M	U	3
DA412	Parts required for fuel presure valve	01/04/2017 05:30	01/04/2017 17:30	M	P	12
DA412	Tyre cut Pos 3	25/04/2017 05:30	07/05/2017 17:30	TUC	P	156
DA412	Check engine stall fault - found loose bleed screw on fuel filter	10/05/2017 11:30	10/05/2017 14:00	M	U	2.5
DA412	Retorque Pos 3 rim after change	11/05/2017 07:30	11/05/2017 08:00	TUC	P	0.5
DA412	Truck shut down on ramp_ electrical fault	17/05/2017 14:00	17/05/2017 16:00	E	U	2

DA412	Engine shutting down - suspect fuel issue	23/05/2017 13:00	23/05/2017 15:00	M	U	2
DA412	Fuel fault	24/05/2017 11:00	24/05/2017 13:00	M	U	2
DA412	Fuel issue - still working through problem	25/05/2017 09:30	25/05/2017 13:00	M	U	3.5
DA412	Fuel problem	03/06/2017 12:00	04/06/2017 15:00	M	U	15
DA412	Still having fuel issues	05/06/2017 13:00	05/06/2017 16:00	M	U	3
DA412	Fire suppression low on gas	12/06/2017 13:00	12/06/2017 14:00	F	U	1
DA412	Gas up fire suppression	13/06/2017 05:30	13/06/2017 06:00	F	P	0.5
DA412	Charge fire suppression	26/06/2017 09:30	26/06/2017 10:30	F	U	1
DA412	Adjust park brake	28/06/2017 11:30	28/06/2017 13:00	D	P	1.5
DA412	Check coolant leak and fire suppression low	06/07/2017 05:30	06/07/2017 07:30	M	P	2
DA412	Tray rolled over	06/07/2017 16:00	07/07/2017 17:30	F	D	13.5
DA412	Pos 2 suspension strut down on gas	08/07/2017 05:30	08/07/2017 11:30	F	P	6
DA412	500hr service and repairs	08/07/2017 11:30	08/07/2017 17:30	S	P	6
DA412	Replace brake accumulator	15/07/2017 05:30	15/07/2017 11:00	D	P	5.5
DA412	Adjust park brake	18/07/2017 13:00	18/07/2017 13:30	D	P	0.5
DA412	Check code coming up on dash	27/07/2017 08:30	27/07/2017 09:30	E	P	1
DA412	Top up fire suppression	03/08/2017 08:30	03/08/2017 09:30	F	P	1
DA412	Top up fire suppression	10/08/2017 13:30	10/08/2017 14:30	F	O	1