

Asset Code	Description	Start	Finish	Category	Delay	Hours
TR228	Backlog and prep for site	01/05/2017 07:00	04/05/2017 17:00	F	P	40
TR228	Transmission harness repair - Tie down points and service	22/05/2017 07:00	26/05/2017 12:00	F	P	45
TR228	TEST TURBO CONTROLLER MALFUNCTION - TROUBLESHOOT - Started at 28/05/2017 10:00:00 AM	29/05/2017 06:30	29/05/2017 18:00	E	O	11.5
TR228	TROUBLE SHOOT UNT CONTROLLER FAULT_STEPPER MOTOR FAULT DIAGNOSIS - EXTERNAL WASTEGATE ACTUATOR REQUIRED	29/05/2017 18:00	06/06/2017 17:00	E	P	190
TR228	A/C fault, Coolant leak and Turbo change out	09/06/2017 07:00	13/06/2017 17:00	F	P	30
TR228	A/C fault, Coolant leak and Turbo change out	09/06/2017 07:00	13/06/2017 17:00	F	P	30
TR228	Replace drivers side window	04/07/2017 07:00	04/07/2017 09:00	F	P	2

NOT VERIFIED