



# Vehicle History Summary

Quadrio Earthmoving

Fleet #	RT24
Registration	CGG713F
Make	Freightliner
Model	Argosy
VIN / Chassis #	1FVNAWBG1DLFB4995
Build Date	2013

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-663	16/04/2019	586352	11131	OIL PRESSURE	Hook up laptop and troubleshoot fault. Hook up blowby too and test drive vehicle. Found blowby at 13inch20 indicating an internal engine fault-possible broken ring set. Oil and filter change as short term fix.	FABBRO DIESEL SERVICES
R-664				ENGINE FAULT		

Signed: \_\_\_\_\_

Name: \_\_\_\_\_

Date: \_\_\_\_\_

NOT VERIFIED