



Vehicle History Summary

Quadrio Earthmoving

Fleet #	RT03
Registration	1EAQ716
Make	Mack
Model	TITAN
VIN / Chassis #	6FMB05E043D708845
Build Date	2003

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-80	12/02/2019	0	6200	B	B Service completed by B.Styns RH headlight blown Air horn not working Air bag for drivers seat needs attention	
R-354	11/01/2019		59708	AIRCON	Fit new compressor and dryer to machine. Put new belts on it, vac down, gas 1.8kg R134A	
I-35	08/01/2019	924102		WAHVA Roadworthy Inspection	Roadworthy completed Drive line clamps tightened Electrical wiring repaired Horn repaired Tightened parking brake.	
I-36	08/01/2019			Wear & Tolerances Inspection/Record	Wear and tolerances inspection complete. See paper copy for details	
R-334	08/01/2019	924102	59408	AIR LEAK, BRAKE VALVE, STUDS	Broken studs completed previously Tank bracket completed previously Air leaks checked previously. Brake valve completed previously. Bonnet mounts completed previously. Repaired wiring in headlights. Repaired broken wire to trailer and tested. Repaired indicators. Checked air con. Roadworthy and wear/tolerances inspection completed.	
T-12	08/01/2019	0	0	New	4x 11R/22.5 tyres fitted by C.Bowran	
S-50	02/12/2018	0	0	A	SERVICE COMPLETE Wiper blades need replacing Requires new engine outer air filter Could not locate leak in air system completed by MJ & Brad	
R-194	30/10/2018			SUSPENSION	wear is within acceptable range	
R-204	30/10/2018	0	0	WINDOW	within acceptable limits	
R-204	30/10/2018			AXLE	inspected cleaned replaced	
R-42	30/10/2018	0	0	SPEEDO	Part ordered-on stock list for Sept/Oct repaired	QUADRIO EARTHMOVING PTY LTD

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-229	28/10/2018	0	0	FIRE EXTINGUISHER	fitted new fire extinguisher	QUADRIO EARTHMOVING PTY LTD
R-205	22/10/2018			AIR LINE, BOLTS, Hydraulics	Repairs carried out by A.Brown	
I-30	20/10/2018			Wear & Tolerances Inspection/Record	No comments made	
S-22	19/10/2018	0	5397	C	2000hr service complete. Oil sump leak Replaced front diff oil only Replace all rear brake shoes unceased all brake cams Replaced rear LH & RH rear mudguards Replaced RH ride height control Fire extinguisher tagged Aug 2018 Service sticker:944100	
R-51	19/10/2018	0	0	AIR BAG, REVERSE ALARM, Suspension	All repairs complete Air pressure was dropping due to hole in air bag. Repaired horn, exhaust & reverse alarm. Fixed hyt control arm on rear diff Replaced sump & gasket Replaced RHR air bag Relined all rear brakes and unceased all S cams	QUADRIO EARTHMOVING PTY LTD
R-181	08/10/2018	0	0	AIRCON, LIGHTS	Aircon re-gassed with 500gms Thermostat compressor adjusted-cycling at 5.8 Headlights has wiring issue under dash-rewired circuit back to original. Harness in bonnet had been rubbing-removed, repaired-fit & test OK Indicators & park lights were shorting-repaired Reverse alarm & light-Replaced sensor in gearbox Checked all rear lights & repaired green death Tested beacon/2way/engine brake/radio/windscreen wipers LH WINDOW MOTOR NEEDS REPLACING	
R-154	25/09/2018		6211	Hydraulics	FITTED BULL HOSE - TAKEN FROM ST08. REFILLED HYDRAULIC TANK	

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-83	20/09/2018	0	5344	AIRCON, INDICATOR, LIGHTS, SPEEDO, WINDSCREEN	Removed high beam fuse & relay panel to access. Hi-beam fuse checked & was OK. Removed hi-beam relay because it wasn't functioning when switch was operated. Replaced relay. High beam now functioning. RH H/light fallen out. Have previously ordered h/light retaining assy but keep getting wrong parts. Removed retainer from wrecked vehicle on dooley downs station & refitted wh H/light/ Windscreen to be ordered. Replaced AC fan motor & fan Lubricated indicator switch so RH indicator operation cancels. Ordering speedo & odo assy	QUADRIO EARTHMOVING PTY LTD
R-43	20/09/2018	0	0	ENGINE BRAKE	Faulty switch. Wrong switch was supplied so made wiring harness and fitted to switch. Tested & works OK	QUADRIO EARTHMOVING PTY LTD
R-88	08/09/2018	0	0	AIR REGULATOR, HORN	Air pressure dropping-checked operation with vehicle not driving. Air pressure holding steady. When vehicle is driven intermittently air pressure drops. Suspect air governor is faulty. Added part to Sept/Oct parts list. No part to repair on site. Operator articulated air horn broke mechanism internally, air horn would not shut off. Had to remove RH side of roof lining to disconnect air supply. Hose kink to stop horn & air leakage. Ordered part. 20/10/2018 Air pressure was dropping due to hole in air bag. Repaired horn, exhaust & reverse alarm. Fixed hyt control arm on rear diff Replaced sump & gasket Replaced RHR air bag Relined all rear brakes and unceased all S cams	QUADRIO EARTHMOVING PTY LTD
R-84	06/09/2018	0	0	CLUTCH	Checked clutch operation & found g/box grating when trying to select 1st or reverse. Checked bearing spacing and found to be slightly wide. Attempted to adjust but mechanism jammed with dust & mud. Cloaned out clutch & bell housing until movement was able to set spacing to 1/2" gap. Adjusted clutch pedal free play to 1 1/2" & checked operation. Still grated slightly. **NOTE** while under vehicle noticed stop clutch quite worn & throughout bearing looked like it hadn't been greased in a while. greased bearing & shaft. Clutch operation now satisfactory.	QUADRIO EARTHMOVING PTY LTD

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-48	31/08/2018	0	0	OIL LEAK	Carried out ENGINE SERVICE & check over. Topped up gearbox oil **NOTE** Gearbox output shaft seal leaking & part was ordered in August- still has not arrived. Topped up front diff levels & checked rear diff **NOTE** 1/2 a tooth was on level plug & oil very dark burnt colour, couldnt drain & replace as all 85W140 haz been used on DZ07 Rewelded turn table lock boss to base and made new lock pin. Removed snapped rear cab stabiliser rod and rewelded, fitted back to cab and chassis mounts	QUADRIO EARTHMOVING PTY LTD
R-32	24/08/2018	0	0	AIR LEAK	REMOVED & REPLACED L/H/R SUSPENSION AIR BAG & RESET RIDE HEIGHTS	QUADRIO EARTHMOVING PTY LTD
R-79	24/08/2018	0	5077	AIR BAG CONTROL, CROSS BAR, HEADLIGHTS, TURN TABLE PINS, WINDSCREEN	TS#0306-JACK UP AIR SUSP & KINKED OFF, /H/R AIR BAG HOSE TO HOLD UP SUSP REMOVED AIR LINE NIPPLE FROM OLD AIR BAG. REMOVED THE 4X MOUNTING BOLTS *ALL WERE SIEZED & TOOK WAY TO LONG TO GET OFF* NEW AIR BAG MOUNTS (LOWER) WERE DIFFERENT SO HAD TO FIND NUTS & MODIFY LOWER AIR BAG PLATE TO SUIT BAG TYPE. FITTED AIR BAG & RESET RIDE HEIGHT AS BEST POSSIBLE AS ALL SUSP HEIGHT CONTROLS ARE OLD & BROKEN.	QUADRIO EARTHMOVING PTY LTD
R-86	28/07/2018	0	0	DOOR HINGE	Unbolted check strap anchor and refitted spring strap back into position- remounted anchor. Seat going up and down without touching control switches. Used silicone liube on control valves and cables to get woroking. **NOTE-will need replacing but when more time can be allocated Fuel leak near filter. Removed delivery hose and elbow from filter housing. Replaced o-ring seal and re-fitted. Adjusted all drive belts. Reinflated RH Steer tyre and LHR drive tyres.	QUADRIO EARTHMOVING PTY LTD

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-19	28/07/2018	0	0	Cab	unbolted, checked strap anchor & refitted spring strap back into position. removed anchor. Seat going up & down without touching control switches. used silicone lube on control valves & cables to get working. Will need replacing when more time is allocated i will remove & strip seat to see if a more permanent fix can be done. Fuel leak near filter. Removed	QUADRIO EARTHMOVING PTY LTD
R-7	28/06/2018			AIRCON, BRAKES, LIGHTS, WINDSCREEN	Carried out ENGINE SERVICE and check over. Trailer light fault was corroded and relays in junction box rear of cab in battery box bypassed relays by bridging circuits with fuses. Replaced low beam relay replaced AC fuse Adjusted all brakes Replaced 2x Rocker box bushes on lead trailer Replaced 2x dolly turntable grease lines	
I-14	22/06/2018			WAHVA Roadworthy Inspection		
R-452	15/02/2018			STEERING	Steering rod installed	
R-433	28/01/2018			AXLE	Removed rear diff axle shaft which had broken	
I-18				Wear & Tolerances Inspection/Record		

Signed: _____

Name: _____

Date: _____