



Vehicle History Summary

Fleet #	RT28
Registration	MI4816
Make	Volvo
Model	
VIN / Chassis #	
Build Date	2009

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-661	17/04/2019	1146083	24741	Power Steering	Dropped bar and tilted cab. Found hose for power steering split. Removed hose, travelled to VCV then pirtek to get new hose. Upon arrival had difficulties fitting hose. Had to die grind lip from both barbs then use flapper wheel to smooth out. Fitting hose took 1.5 hours. Filled power steering oil and primed up system. Degreased and washed LHS of engine. Dropped cab and test drive-all good. Hooked up pressure cooling system. Pumped up system pressure and found 4x leaks. Drained all coolant from system. Removed and replaced both hoses next to radiator LHS for transmission cooler. Also shortened up hoses. Removed bottom radiator hose, hose clamps, resealed fitting on compressor. Removed and replaced o-ring on hose behind head. Refilled system and pressure tested. No leaks-all good. Air compressor intake hose needs resecuring. All belts starting to split Mud guard brackets on steers need re-securing.	FABBRO DIESEL SERVICES
R-662				BELTS, HOSE		

Signed: _____
 Name: _____
 Date: _____