



0236

GROUND SUPPORT SYSTEMS (AUST)

SERVICE/INSPECTION REPORT

Machine Type: Moxy Water Cart
Serial No.:
Hours/Km's: 17909
Service Location: Madelington

Plant No.: WC25
Date of Service: 24/01/2019
Mechanic: RBZ
Signature: [Signature]

- No Fault Found
Fault Found and Corrected

- Follow up Required
Job Strongly Recommended

Table with 5 columns: Engine, 250, 500, 750, 1000. Rows include: Precleaner Clean, Engine Mount Security, Oil and Filter Change, Fuel Filter Element Change, Coolant Level and Strength, Radiator - Clean, Air Cleaner Dust Valve, Air Cleaner Outer Change, Fuel Lift Pump - Clean, Fan Belt Tension/Condition, Air Cleaner Inner Change, Fuel Sedimenter - Drain, Engine Oil Sample, Fuel Tank Drain Water / Sediment, Transmission, Security of Mount Bolts and Nuts, Track Gearbox Oil Level, Slew Gearbox Oil Level, Track and Slew Gearbox Oil Change, Track and Slew Gearbox Oil Sample, Slew Gear - Grease, Hydraulics, Servo Filter Element - Change, Oil Sample (Change of required), Oil Sample, Oil Level, Return Filter Element Change, Drain Filter Element Change, Tank - Drain Water and Deposits, Oil Cooler - Clean/Check Damage, Grader, Check L/H Chain Case Level, Check R/H Chain Case Level, Check Blade Slew G/Box Level, Check Blade Slides for Wear, Check Cutting Edge.

Table with 5 columns: Undercarriage, 250, 500, 750, 1000. Rows include: Track Roller Oil - Leakage, Idler Wheels - Leakage, Track Plate Condition and Torque, Body and Framework, All Hinges - Lubricate, All Pivot Pins - Check / Grease, Slew Ring - Grease, Slew Ring Teeth - Grease, Bucket Pivot Pin Grease Seal Check, Cab, Fill windscreen washer bottle, A/C Filter Clean, Seat Belt - Condition/Security, Paintwork, Condition (Diagram), Slew Operation, Slew Brake Operation, Operation All Services, Accumulator - Operation, Hoses - Damage or Leaks, Pipework - Damage or Leaks, Piston Rods and Gland Seals, Starter Motor, Alternator, Warning Lights, Lights and Instrument, Wipers, Refuel Pump, Track / Track Operation, Measure Track Wear, Teeth an Side Cutters, Doors and Canopy, Locks, Attachment Operation, Overload Warning Check Function.

Note
* Service Report is to be completed at the service location
* Completed service reports are to be returned to the head office within 1 day of the service



0236

GROUND SUPPORT SYSTEMS (AUST)

SERVICE/INSPECTION REPORT

Electrics	250	500	750	1000
Battery Terminals - Condition	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Battery Electrolyte Level - Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Wiring for Chafing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Functional Test	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Headlights	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Indicators	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Brake Lights	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Reverse Beeper	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Motion Beeper	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Flashing Light	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Final Inspection	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Loader Final Drivers				
Check L/H Planetary	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Check R/H Planetary	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Check Front Diff	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Check Rear Diff	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Change Oil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Brakes	250	500	750	1000
Front	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Front Tandem	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Tandem	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission - Loader				
Change Transmission Filter	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Change Transmission Oil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Check Oil Cooler	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Check Suction Screen	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission Oil Level	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Drive Line	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Universal Joints	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Park Brake Lining	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Marks / Action Implemented During Service

C/O Front strut
C/O Hydraulic Pump
Replace suction hoses, Replace Hyd & Brake cooling oil
C/O Trans & Diff Breathers
C/O POS 3 wheel bearings and duo seats

Marks / Action Implemented During Service



GROUND SUPPORT SYSTEMS (AUST)

PLANT MAINTENANCE / REPAIR SHEET

Machine Type: Moxy Water Cart
Make / Model: Bell B40D
Serial No: _____
Service Location: Maddelington

Plant No: WC25
Date of Service: 30/01/2019
Hours / Kms: 17909
Mechanic: Robin

WORK UNDERTAKEN

1000hr Service & Mechanical Inspection
Remove hyd pump from DT25 and fit to WC25
Remove front struts from DT26 and fit to WC25
Replace POS 3 wheel bearings and Duo Seal
Replace water Actuator Air lines
Replace hyd suction Hoses and oil

SCHEDULED SERVICE: YES / NO REPAIR: YES / NO
OIL SAMPLE TAKEN*: YES / NO OTHER: _____

*Oil sample every 250 hours for engine, 5000 hours for all other components.

IF REPAIR, STATE THE CAUSE OF DAMAGE OR FAILURE _____

PARTS USED

DESCRIPTION	PART No.

WORK DONE BY
NAME Robin

DATE 31/01/2019

WORK APPROVED BY
NAME _____

DATE _____